

## Staveley with Ings Emergency Action Plan (Appendix 6)

### Monitoring Log of Serious Flood Incidents (2020 onwards)

Note: December 2015 (Storm Desmond) incidents only included in main log if on-going (potentially or actual) or remedial action unknown. Historical list of 2015 incidents included below for reference in case of future severe incident. Illustrations of incidents also available in WhatsApp photo record.

Location	Post code	Brief description of problem	Date of first report	Brief description of latest incidents	Date of re-occurrence	Potential (P) or actual (A) flood impact	Remedial work undertaken	Date of remedial work	Date incident closed
Stockbridge Farm	LA89LP	Foul water discharge from manhole	30.9.17 (on this record, also Dec '15)	Continuing discharge in very heavy rainfall	11.10.17 then a further 11 times to 24.2.20 1.11.20 23.2.21	Foul water into SSSI river (A) Danger to health (P)	Checking of system; clearance of any blockage  Minor repairs within village drainage system	Regular  Reported on Jan 2020	
Gowan Terrace	LA89LW	Foul water discharge from manhole	11.10.17 (on this record, also Dec '15)	Continuing discharge in very heavy rainfall	22.11.17 then a further 9 times to 24.2.20 1.11.20 23.2.21	Foul water into SSSI river (A) Danger to health (P)	Checking of system; clearance of any blockage  Minor repairs within village drainage system	Reported on Jan 2020	
Kendal Road	LA89LP	Foul water discharge from 3 manholes from Stockbridge to Eagle & Child	9.2.20	Continuing discharge in very heavy rainfall  One only: Barrow Bank	As above 15.2.20  24.2.21	Foul water into SSSI river (A) Danger to health (P)	Checking of system; clearance of any blockage  Minor repairs within village drainage system	Reported on Jan 2020	
85 Main St (by Pavillion)	LA89LN	Foul water discharge from manhole	22.11.17 (on this record,	Continuing discharge in very heavy rainfall	15.2.20  20.2.20	Foul water into SSSI river (A) Danger to health (P)	Checking of system  Minor repairs within	Reported	

			also Dec '15)				village drainage system Non-return valve to be fitted on private property	on Jan 2020	
Springwell & Yew Tree Cottages	LA89NE	Foul water discharge on private property	On-going	Historically in very heavy rainfall		Foul water into SSSI river (A) Danger to health (P)	As above		
Main Street from Nos. 67 & 38 upwards	LA89LN	Flooding from road by Gowan, back up of drains, surface water seepage from Rec	5.12.15			Damage to property (A)	New bridge, bund lowered on Kent, gravel removed	2017	<b>Closed</b>
Gowan Terrace	LA89LW	Flooding from road by Gowan, back up of drains, water in cellars	5.12.15	Road flooded in part to garden gates, some back up of drain by 1 Gowan Terrace	9.2.20 15.2.20	Damage to property (P)	New bridge, bund lowered on Kent, gravel removed	2017	
Stockbridge/ Caldriigg Fold Culvert	LA98LP	Culvert over-run, culvert and bridge damaged, flooding and debris onto road	5.12.15	Culvert over-run	9.2.20 15.2.20	Road flooding (A) Danger to traffic (A)	New culvert and bridge installed over stream	2016	
Station Road/Beck Nook	LA89NB	Manhole discharging by Lily Brook, flooding across road, into 3/5 Station Rd; additional flooding danger from traffic flow	9.2.20	As previously	15.2.20 1.11.20	Road flooding (A) Damage to property (P) Trip hazard (A)			
Seedfield, No. 39 and neighbouring property	LA89NJ	Back up of foul water causing blockage in extremely heavy rain conditions	17.1.21 (to Parish Council)	As described. Incidents on private property date back many years but are increasing in frequency	To be recorded in future	Damage to property (P)	Reported to UU but no solution. Regular rodding by owner. Reduced water pressure also reported	On-going	
Seedfield/ Crookfield field	LA89QS	Surface water from field between Crookfield & Seedfield spilling into road	9.2.20			Road flooding lower down on Station Road (A)			
Kendal Road footway	LA98LP	Surface water and overflow from manholes and culvert ponding on path & road	9.2.20	As previously	15.2.20	Footway damage (A) Danger to traffic (A)			
Silver Street	LA89NX	Back up through manholes and drains	5.12.15			Damage to property (A)	Non-return valve fitted, drain clearance	2017	<b>Closed</b>
Raven Garth	LA89PG	Surface water cascading from land above, through gardens and driveways of Whitber, Fernghyll and on	5.12.15	Continuing in heavy rainfall, including and in addition to flood conditions	12.3.19 + previously	Damage to property (P) Road hazard (P)	Discussion with CCC and landowners – action awaited		

		to Kentmere Rd			On-going – see separate log		Investigation camera work by CCC. Repair to pipe from field in Fernghyll	Jan 2021	
Bridge House/Lane End Cottage	LA89PQ	Surface water cascading from land above & over culvert	9.2.20			Damage to property (P)			
Poor Field, Staveley	LA8 9PH	Flow of surface water from higher ground	9.2.20	New channels gorged through fields (e.g. Poor Field) Increase in surface water through field on to Brow Lane	17.2.20	Damage to property (P) Damage to highway (P)  24.2.21			
Rawes Garth entrance	LA89PH	Water erupting through pavement and main road	24.2.21			Damage to road/pathway – tarmac lifted (A)	Reported to UU; under investigation for burst pipe: 24.2.21		
St James's Church, Boiler House	LA89PA	Heavy flooding of boiler house (below ground) caused by seepage of surface water	5.12.15	As previously	9.2.20	Damage to property (P)			
Heywood, Kentmere Rd.	LA89JF	Flooding of property from surface water from higher ground	5.12.15			Damage to property (A) Road flooding (A)	New road culvert installed	2016	<b>Closed</b>
Road damage (general)	-								

Latest update: 17.1.21

**December 2015: Historical list of Incidents (if not included above)**

Eagle and Child bridge destroyed: new bridge installed May 2017

Station Road bridge, minor damage: checked as safe 2015

Barley Bridge and Kentmere Packaging, minor damage to bridge, major damage to Kentmere: bridge awaiting repair, refitting within factory, flood gates fitted

Scroggs Bridge and cottages, major damage to bridge and access road to cottages: major repairs to bridge and new safety measures, include widening of road and turning to access bridge, 2016

River Gowan below water foundations, damage to water course boundary along stretch of river: major repairs and reinforcement under normal water level, 2016

Gowan Close river bank, major damage to garden walls bordering river: major repairs completed, 2016

Scroggs Farm, flooding in house: repair not known but house more recently rebuilt as inadequate foundations revealed

Brow Lane properties, minor flooding of some properties from surface water run-off: response not known

Reston Mill properties, minor flooding of properties: extent of response not known

Beck Nook No. 62 and garages by No. 32: some minor flooding

New pedestrian bridge by Mill Yard, damage to river bank and footpath: rebuilt 2016

Meadowcroft, Ings, flooding of property; Almshouses, Ings, flooding of properties

Watermill Inn, Ings, flooding of property: ground floor and kitchen refitted